

# Protective Equipment Checklist

Always perform a *Hazard Risk Assessment* to determine your safety requirements before starting any job (Refer to OSHA standard 1910.331-335).

Hazard Risk Category	Clothing Description	Minimum APTV Rating Cal/cm2
0	Untreated Cotton, Wool, Rayon, Silk, or Blend. Fabric weight >4.5oz/Yd2 (1 layer)	N/A
1	FR Shirt and FR Pants or FR Coverall (1 layer)	4
2	Cotton underwear plus FR shirt & FR pants (1 or 2 layers)	8
3	Cotton underwear plus FR shirt & FR pants plus FR coverall, cotton underwear plus two FR Coveralls (2 or 3 layers)	25
4	Cotton underwear plus FR shirt and FR pants plus multilayer flash suit (3 or more layers)	40

## Head and Face Protection:

- Hood
- Hard Hat with Face Shield
- Safety Glasses
- Balaclava (Sock Hood)

## Body and Leg Protection:

- Shirt
- Pants
- Parka
- Bib Overalls or Coveralls
- Cooling Vest and Gel Packs

## Hand Protection:

- Insulating Rubber Gloves
- Glove Protectors

## Storage Bag

## Insulated Tools

## Miscellaneous:

- Blankets with clamps
- Rubber Matting
- Hot Sticks and Rescue Hooks

***Cementex***