

Arc Flash Warning Labels

Comply with NEC marking requirement for arc flash hazard protection with arc flash safety labels.

Arc Flash Labels are laminated for durability and protect your message against weather, abrasion, and chemicals.

WARNING

Arc flash / Shock hazard!
Observe approach boundaries.

May shock, burn or cause death.

___ Flash hazard boundary - must wear appropriate PPE.
___ Cal/cm² flash hazard at 18"
___ Hazard/Risk category (0-4)

Nominal system voltage range, phase to phase: ___ kV to ___ kV
___ Limited approach boundary ___ Movable: ___ fixed: ___
___ Restricted approach boundary ___
___ Prohibited approach boundary ___

Equipment name: _____
By: _____ Date: _____

U5070W-ARKFLS [Dc <50V (NFPA 70E (04) 67-69)]

CP-AFWL

WARNING

Qualified Persons Only

Arc Flash and Shock Hazard.
Appropriate PPE Required.
When exposed to energized components.

NFPA 70E Hazard Level ___

___ Flash Protection Boundary
___ Shock Hazard when ___
Use ___ insulating gloves when working within
___ of exposed energized components

U625875-IGZ
Uicom Systems Inc.
800-548-5321

Last Review Date: ___ By: ___
Bldg. ___ Equipment Names: _____

CP-AFWL-QP

WARNING

Arc flash and
shock hazard.
Appropriate PPE
required

▲ USI U3550WFP-I

CP-AFWL-AB

Part Number	Description
CP-AFWL	Arc Flash Warning Label (3.5" x 5")
CP-AFWL-AB	Approach Boundary Arc Flash Warning Label (5" x 7")
CP-AFWL-QP	Qualified Persons Arc Flash Warning Label (5.25" x 8.75")